



Material and Procurement Services / Services du matériel et des acquisitions
Procurement Hub – Ottawa/ Centre d’approvisionnement – bureau de Ottawa
200 Kent Street | 200 rue Kent
Ottawa, ON, K1A 0E6

30004672

28 March / mars, 2024

Subject/ Object: INVITATION TO TENDER / APPEL D’OFFRES 30004672

ADDENDUM #002 / ADDENDA N° 002

Further to the above- mentioned Invitation to Tender documentation previously forwarded to your firm, Addendum #002 is hereby issued.

Pour faire suite à la documentation d’accompagnement de l’appel d’offres susmentionné transmise à votre entreprise, l’Addenda n° 002 est émis.

Questions and Answers

Q1. The specification provided calls for 9” row spacers however based on calculations done by the bidder and the drawing that was supplied they are saying that this would not work. I’ve attached their own internal drawing as reference they are saying that based on the 8” building columns and the requested aisle widths for forklift access they expect that the row spacer should be 34”? Can you please advise if this is an error in initial drawings included in the tender or if the bidder is mistaken with their measurements?

A1. The error is in the specification.

ADDENDUM:

Annex C SPECIFICATIONS - attachment Specs-Bldg 25 Pallet Racking_Jan232024.pdf

Section 01 11 00 – SUMMARY OF WORK

Section 1.6.6 Accessories

DELETE: .1 Row spacers at every two levels, 9” long for back to back pallet racks

INSERT: 1 Row spacers at every two levels, 34” long for back to back pallet racks as per drawings

Questions et réponses:

Q1. Les spécifications fournies prévoient des espaceurs de 9 pouces, mais selon le soumissionnaire qui a effectué des calculs et le dessin fourni, cela ne fonctionnerait pas. J'ai joint son propre dessin à titre de référence. Il dit que d'après les colonnes de 8 po et des largeurs d'allée nécessaires pour l'accès des chariots élévateurs, il suppose que l'espaceur de rangée devrait être de 34. Pouvez-vous indiquer s'il s'agit d'une erreur dans les dessins initiaux compris dans l'appel d'offres ou si le soumissionnaire s'est trompé dans ses mesures?

R1. L'erreur se trouve dans les spécifications.

ADDENDA

ANNEXE C – SPÉCIFICATIONS - pièce jointe “FR_Specs-Bldg 25 Pallet Racking_IFT_Jan232024.pdf

SECTION 01 11 00 – SOMMAIRE DES TRAVAUX

Section 1.6.6 Accessoires

SUPPRIMER: .1 Espaceurs de rangée tous les deux niveaux, 9 po de longueur pour les palettiers dos à dos

INSÉRER: .1 Espaceurs de rangée tous les deux niveaux, 34 po de longueur pour les palettiers dos à, dos conformément aux dessins

**All other Terms and Conditions for this requirement remain unchanged.
Toutes les autres modalités de la présente exigence demeurent inchangées.**

Yours Truly,

Veillez agréer, Monsieur/Madame, l'expression de mes sentiments les meilleurs,

Paul Fortier
Contracting Specialist NCR Hub / spécialiste des contrats centre d'approvisionnement