

**RFB 100033569
AMENDMENT 005**

Questions & Answers:

Question 14	Please confirm the ceiling height in the affected areas.
Answer 14	The ceiling height in the affected areas is 115 inches.