

APPENDIX B



PHOTO No.01




PHOTO No.02



PHOTO No.03



PHOTO No.04



PHOTO No.05



PHOTO No.06



APPENDIX B




PHOTO No.07



PHOTO No.08

Health Canada Lab/Operations Technicians have removed a section of copper rad run. Photos No.07 and No.08



PHOTO No.09

Existing/removed motorized valve body Photos No.09 and No.10



PHOTO No.10



Existing condition of the inside of the COPPER RAD SECTION that was removed. Photo No.11

PHOTO No.11



Health
Canada

Santé
Canada

APPENDIX B

PHOTOS (taken Thursday April 27, 2023) – TYPICAL COPPER LINES, FIN RADS and SIEMENS motorized valves

